

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

### Reclamation District No. 0554 Walnut Grove

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.13	03/16/2016 03/16/2016	Herman Phillips

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0554_01_f_2014_3				
Comment Code					
Inspector Comment					
The district is prepared to partner with neighboring Districts as in the past.					

No Photos

LM Start		Rating **	A	Issue No.	35
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0554_01_f_2014_35				
Comment Code					
Inspector Comment					
The district has the O&M Manual on hand.					

No Photos

LM Start		Rating **	A	Issue No.	36
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0554_01_f_2014_36				
Comment Code					
Inspector Comment					
The district shares with neighboring district, RD 551.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

### Reclamation District No. 0554 Walnut Grove

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.13	03/16/2016 03/16/2016	Herman Phillips

LM Start	0.05	Rating **	M	Issue No.	32
LM End	0.39	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.249050 °	38.244495 °
				-121.509977 °	-121.511830 °
DWR ID	DWR_RD0554_01_f_2015_32				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
This section on the waterside has growth covering the fence at levee mile 0.05 and vegetation on the slope.					

Photo 1 of 1 : SP\_2016\_RD0554\_176\_32\_20160316\_00053.jpg



RD 554 Levee mile 0.05 waterside shoulder.

LM Start	0.09	Rating **	A	Issue No.	31
LM End	0.56	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.248450 °	38.242447 °
				-121.509945 °	-121.513717 °
DWR ID	DWR_RD0554_01_s_2016_31				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	0.10	Rating **	U	Issue No.	11
LM End	0.10	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.248262 °	38.248262 °
				-121.509901 °	-121.509901 °
DWR ID	DWR_RD0554_01_s_2014_11				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
This is not a new erosion site, repairs are needed. One tree has fallen into the Sac River at the erosion site. This site can be seen better from the river by boat. The wild grapes blocks the view from the waterside shoulder looking down the slope. There was no new picture taken of this issue.					

Photo 1 of 1 : SP\_2016\_RD0554\_176\_11\_20160223\_00003.jpg



Erosion on waterside toe dead tree fallen at erosion site.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

### Reclamation District No. 0554 Walnut Grove

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.13	03/16/2016 03/16/2016	Herman Phillips

LM Start	0.26	Rating **	M	Issue No.	1
LM End	0.36	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			38.246222 °	38.245017 °
				-121.510878 °	-121.511740 °
DWR ID	DWR_RD0554_01_s_2016_1				
Comment Code					
Inspector Comment					
2009 - Tension cracks on road on top of levee. Erosion into the levee slope and mass failure. 2013 - Short vertical sections at bank toe. 2015: No observed changes. [2015 Site ID: SAC_27-0_L]					

LM Start	<b>0.26</b>	Rating **	M	Issue No.	<b>1 (cont)</b>
LM End	<b>0.36</b>	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : SP\_2016\_RD0554\_176\_1\_20160223\_00001.jpg



USACE 2013 Photo #1

Photo 2 of 2 : SP\_2016\_RD0554\_176\_1\_20160223\_00002.jpg



USACE 2013 Photo #2

LM Start	0.32	Rating **	U	Issue No.	13
LM End	0.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.245389 °	38.245389 °
				-121.511085 °	-121.511085 °
DWR ID	DWR_RD0554_01_s_2014_13				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
The District has scheduled repairs this season.					

Photo 1 of 1 : SP\_2016\_RD0554\_176\_13\_20160223\_00004.jpg



This erosion along the landside levee slope is not new, it was reported two years ago.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown		<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable		<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

### Reclamation District No. 0554 Walnut Grove

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.13	03/16/2016 03/16/2016	Herman Phillips

LM Start	0.77	Rating **	U	Issue No.	20
LM End	0.81	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.240128 °	38.239630 °
				-121.515974 °	-121.516418 °
DWR ID	DWR_RD0554_01_s_2014_20				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Control the tall weeds and remove these fig trees from the landside slope.					

Photo 1 of 1 : SP\_2016\_RD0554\_176\_20\_20160316\_00054.jpg



Woody tree growth on the landside shoulder and slope. Also tall grasses at this location.

LM Start	0.81	Rating **	M	Issue No.	38	
LM End	0.96	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Vegetation			38.239568 °		38.237602 °
				-121.516452 °		-121.516755 °
DWR ID	DWR_RD0554_01_s_2016_38					
Comment Code						
V1 : Control annual grass and weeds on the levee slopes and easements.						
Inspector Comment						

No Photos

LM Start	0.82	Rating **	M	Issue No.	33
LM End	1.11	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.239527 °	38.235337 °
				-121.516440 °	-121.517170 °
DWR ID	DWR_RD0554_01_f_2015_33				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The District has scheduled to have the vegetation on the water side slope sprayed.					

No Photos

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

### Reclamation District No. 0554 Walnut Grove

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	1.13	03/16/2016 03/16/2016	Herman Phillips

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---